

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER
AECOM'S EAST ASH POND VISUAL SITE INSPECTION REPORT - 2019**

Documented to meet 257.83(b)(5)

	DEFICIENCY/OBSERVATION (inspection recommendation #)	CORRECTIVE MEASURE
1	Minor erosion rills on embankments on the downstream side of the crest's edge.	The area was regraded.
2	Some high grass and vegetation growth noted on south embankment slope.	The vegetation was removed.
3	CCR material accumulation aboved the crest elevation is currently preent on the interior side of the south embankment.	Material removed to a level below crest elevation.