## RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER AECOM'S EAST ASH POND VISUAL SITE INSPECTION REPORT - 2021 Documented to meet 257.83(b)(5)

DEFICIENCY/OBSERVATION (inspection recommendation #)	CORRECTIVE MEASURE
No deficiencies observed.	