

**RESPONSE TO ASH POND OBSERVATIONS AND RECOMMENDATIONS PER
AECOM'S WEST ASH POND VISUAL SITE INSPECTION REPORT - 2017**

Documented to meet 257.83(b)(5)

	DEFICIENCY/OBSERVATION (inspection recommendation #)	CORRECTIVE MEASURE
1	Interior Slope - Near vertical side slopes are present where ash appears to be collapsing into basin adjacent to access road.	Slope was regraded and new riprap was installed.
2	Exterior Slope - A few small trees, bushes, and brush have grown on the embankment slope.	Vegetation sprayed